

Ram Truck 1500K 4WD

Differential Housing Repair / RHS, 2012-up
INTERMEDIATE SHAFT - REPAIR KIT
CH-3511RK

OE PROBLEM

Clunking (or) vibration noises when trying to apply 4WD. The dashboard light indicates the Shift Actuator is working but it will not engage in 4WD. Issue: The front differential RHS (right hand side) Intermediate Shaft to CV inboard joint splines are stripped which also causes a bearing failure.



CUSTOMER ALERT / RECOMMENDATION:

The original connecting CV Shaft could also be defective if the intermediate shaft is damaged and should be replaced.

We strongly Recommend Replacing the CV Shaft with a new TrakMotive CH-8256, CH-8256HDX or CH-8256XTT when completing the job.

Do the job right the first time and save time, money, and aggravation down the road!



OE Replacement CV Axle

Note: If "upgrading" to the CH-8256HDX (or) CH-8256XTT, the CV Axles should be installed in Pairs (Left & Right) to ensure proper performance.



Improving OE Quality by Design